


DARK BROWN SILTY TOPSOIL
CONTAINING OCCASIONAL MEDIUM
SIZED ROUNDED AND ANGULAR
GRAVELS WITH ROOTLETS THROUGHOUT.

FRACTURED SHALE BEDROCK,
BECOMING MORE FIRM WITH DEPTH.



DRAWING No.:		PROJECT:		ORIGINATOR:		DATE:		SCALE:		ORIGINAL SIZE:		DRAWING TITLE:	
09422		CCE		V1 XX		40:40:01		C		LAND ADJ TO CROWN STREET, GWALCHMAI		TP3 TRAIL PIT LOG	
50:30		0015		S1		P01							
M.Jones		20.06.2022		1:25		A4							
CLASSIFICATION		No.		SUITABILITY		REVISION							

CADARN
CONSULTING ENGINEERS

Address: CADARN Consulting Engineers Ltd,
Suite B,
Anglesey Business Centre,
Bryn Cefni,
Llangefni,
LL77 7XA

E-mail: Admin@cadarnconsulting.co.uk

Tel: 01407 730912

Sl	Rev	Date	Description	Chg	Chkd	App'd	Auth'd