DARK BROWN SILTY TOPSOIL CONTAINING OCCASIONAL MEDIUM SIZED ROUNDED AND ANGULAR GRAVELS WITH ROOTLETS THROUGHOUT.

VERY FIRM, LIGHT BROWN/ORANGE VERY GRAVELY, SLIGHTLY CLAYEY SLIGHTLY SANDY, **SILT**. GRAVELS ARE VERY FINE TO MEDIUM SIZED ANGULAR GRAVEL.

VERY FIRM, LIGHT BROWN/ORANGE VERY GRAVELY, SLIGHTLY CLAYEY SLIGHTLY SANDY, **SILT**. GRAVELS ARE VERY FINE TO LARGE SIZED ANGULAR GRAVEL WITH OCCASIONAL BOULDERS EXCEEDING 200mm DIAMETER.

SLIGHT SEEPAGE OF GROUND WATER IDENTIFIED AT BOTTOM OF TRAIL HOLE, AT 3.060m DEEP.



S1	P01	09.06.22	DESCRIPTION				
SUIT	REV	DATE	DESCRIPTION	Org.	Chk'd	App'd	Auth'd

DRAWING STATUS:

DRAWING No.:

PROJECT	ORIGINATOR	VOL.	LOC.	TYPE	ROLE
09422	CCE	V1	XX	40:40:01	C
50:30		0013	S1	P01	
CLASSIFICATION		No.	SUITABILITY	REVISION	

PROJECT TITLE: LAND ADJ TO CROWN STREET, GWALCHMAI

ORIGINATOR:	DATE:	SCALE:	ORIGINAL SIZE:
M.Jones	20.06.2022	1:25	A4

DRAWING TITLE: **TP1** TRAIL PIT LOG

CADARN CONSULTING ENGINEERS

Address: CADARN Consulting Engineers Ltd, Suite B, Anglesey Business Centre, Bryn Cefni, Llangefni, LL77 7XA

Tel: 01407 730912

E-mail: Admin@cadarnconsulting.co.uk